



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Col/S\$

U.S. Patent No.: 7,025,407 B2

Serial No. : 10/690,723

Filed : October 22, 2003

Issued : April 11, 2006

For : MINING HOPPER MADE UP OF STEEL AND POLYMERS

**PETITION FOR CERTIFICATE OF CORRECTION  
PURSUANT TO 37 C.F.R. § 1.322 OR § 1.323**

Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

**Certificate  
JUL 13 2006  
of Correction**

Sir:

Applicants hereby request that the above-identified U.S. patent be corrected in accordance with the attached Certificate of Correction.

I. C.F.R. § 1.322

- ☐ The mistake(s) was/were incurred through the fault of the Patent and Trademark Office and is/are clearly disclosed in the records of the Office. Therefore, no fee is due.

II. C.F.R. § 1.323

- ☒ At least some of the mistakes were made by the applicant. Therefore, a check in the amount of \$100.00 in payment of the fee set forth in 37 C.F.R. § 1.20(a) is enclosed herewith.

Enclosed herewith is a Form PTO-1050 (in duplicate) listing errors that have been found in the above-identified patent. The error(s) are of a clerical or typographical nature or of minor character and were made in good faith. The requested correction(s) do not constitute new matter or require reexamination.

07/12/2006 RMEBRAHT 00000033 7025407


01 FC:1811

100.00 OP

JUL 13 2006

III. Accordingly, patentees and their assignee respectfully request that the Patent and Trademark Office issue a Certificate of Correction pursuant to 37 C.F.R. § 1.322 or § 1.323, respectively.

Respectfully submitted,



---

Harry B. Shubin, Reg. No. 32,004  
Attorney for Applicants

MILLEN, WHITE, ZELANO  
& BRANIGAN, P.C.  
Arlington Courthouse Plaza 1  
2200 Clarendon Blvd. Suite 1400  
Arlington, Virginia 22201  
Telephone: (703) 243-6333  
Facsimile: (703) 243-6410

Attorney Docket No.: CAREY-0012

Date: July 10, 2006

301-18 2006

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.  
(Also Form PTO-1050)

## UNITED STATES PATENT AND TRADEMARK OFFICE

### CERTIFICATE OF CORRECTION

PATENT NO : 7,025,407 B2

DATED : April 11, 2006

INVENTOR(S) : Manuel Antonio MEDEL

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

On the front page, Foreign Application Priority Data: reads "73-2003" should read -- 0873-2003 --  
Column 7, line 11, reads "beams, said transverse beams, said" should read -- beams, said --  
Column 7, line 23-24, read "elastomericropes" should read -- elastomeric ropes --  
Column 8, line 8, reads "a front wall portions" should read -- front wall portions --  
Column 8, line 10, reads "polymers comprises" should read -- polymers comprise --  
Column 8, line 11, reads "mining hoppers said" should read -- mining hopper, said --  
Column 8, line 21, reads "side walls front selection" should read -- side walls, front section --

MAILING ADDRESS OF SENDER: Millen, White, Zelano & Branigan  
2200 Clarendon Blvd. Suite 1400  
Arlington, VA 22201

PATENT NO. 7,025,407

No. of additional copies



Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary depending upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, Washington, DC 20231.

JUL 13 2006